

**Photo 1**



View of the stabilized construction entrance—facing west.

**Photo 2**



View of the erosion control breach—facing northwest.

**PHOTOGRAPHIC DOCUMENTATION**

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 07.28.2021

**Photo 3**



View erosion gullies beginning to form upgradient of the informal northern access road—facing northwest.

**Photo 4**



View of erosion within the access road to the north of the stockpile area—facing north.

**PHOTOGRAPHIC DOCUMENTATION**

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 07.28.2021