

Photo 1



View of the recently maintained construction entrance—facing north.

Photo 2



View of hydroseed within the stockpile area—facing southwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021

Photo 3



View of hydroseed within the access road—facing east.

Photo 4



View of hydroseed applied to exposed soils to the southwest of the timber mats—facing northwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021

Photo 5



View of re-established straw wattles—facing north.

Photo 6



View of an area where sediment was removed from beyond the limits of work and seed was applied—facing north.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021

Photo 7



View of erosion channels and exposed soils within and along the equipment tracks present at the informal access road near the northern limits of work—facing northwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021