

Photo 1



View of the recently maintained construction entrance—facing north.

Photo 2



View of hydroseed within the stockpile area—facing southwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021

Photo 3



View of hydroseed within the access road—facing east.

Photo 4



View of hydroseed applied to exposed soils to the southwest of the timber mats—facing northwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021

Photo 5



View of re-established straw wattles, rather than installation of a compost filter tube—facing north.

Photo 6



View of the siltation fencing incorrectly re-installed.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021

Photo 7



View of sediment removed from beyond the limits of work, and seed applied—facing north.

Photo 8



View of erosion gullies and exposed soils resulting from the informal access road along the northern limits of work—facing northwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.11.2021