

Photo 1



View of conditions within the access road leading to the stockpile area—facing south.

Photo 2



View of germination within the stockpile area—facing northeast.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.20.2021

Photo 3



View of ponding water within the area of the former erosion control breach—facing north-west.

Photo 4



View of evidence of stormwater flowing under the siltation fencing and discharging downgradient of the limits of work.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.20.2021

Photo 5



View of an area contributing runoff to the area of the former erosion control breach; note the channel forming to the left of the timber mats—facing northwest.

Photo 6



View of the area to the south of the former erosion control breach that appears to also contribute runoff to that segment of erosion controls—facing southeast.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.20.2021

Photo 7



View of erosion channels and exposed soils within and along the equipment tracks present at the informal access road near the northern limits of work—facing northwest.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.20.2021