

**Photo 1**



View of exposed soils along the west side of the stabilized construction entrance—facing west.

**Photo 2**



View of scour associated with the aforementioned exposed soils at the construction entrance; all scour is confined to the limits of work—facing southwest.

**PHOTOGRAPHIC DOCUMENTATION**

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.23.2021



**Photo 3**



View of the earthen access road—facing south.

**Photo 4**



View of runoff undercutting the siltation fencing at the location of the former erosion control breach (Discharge 1) - facing southwest.

**PHOTOGRAPHIC DOCUMENTATION**

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.23.2021



**Photo 5**



View of scour forming just upgradient of the off-site Vegetated Wetland—facing east.

**Photo 6**



View of erosion channels at the location of the informal access path along the northern limits of work—facing northwest.

**PHOTOGRAPHIC DOCUMENTATION**

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.23.2021



**Photo 7**



View of ponding associated with the runoff flowing down the previously depicted informal access path—facing northwest.

**Photo 8**



View of scour just beyond the northern limits of work due to runoff undercutting the siltation fencing (Discharge 2)—facing north.

**PHOTOGRAPHIC DOCUMENTATION**

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.23.2021