

Photo 1



View of the repaired erosion control measures associated with Discharge 1—facing north-west.

Photo 2



View of stabilization measures implemented beyond the limits of work at the location of Discharge 1—facing south.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.24.2021

Photo 3



View of the repaired erosion control breach associated with Discharge 2; note the stabilization of exposed soils beyond the limits of work—facing northeast.

Photo 4



View of exposed soils stabilized at the construction entrance; note the implementation of straw bales—facing south.

PHOTOGRAPHIC DOCUMENTATION

North Sturbridge Road Solar Facility

Charlton, Massachusetts

Photographs Documented 08.24.2021