

Photo 1



View of the damage erosion control measures associated with Discharge 2—facing north.

Photo 2



View of area downgradient of Discharge 2—facing west.

PHOTOGRAPHIC DOCUMENTATION  
North Sturbridge Road Solar Facility  
Charlton, Massachusetts  
Photographs Documented 09.02.2021

Photo 3



View of the damaged silt fence in southern perimeter of Site —facing south.

Photo 4



View of degraded straw wattle at southeast perimeter of Site —facing east.

PHOTOGRAPHIC DOCUMENTATION  
North Sturbridge Road Solar Facility  
Charlton, Massachusetts  
Photographs Documented 09.02.2021