Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 03/15/2022

			General Info	ormation		
Weather conditions during inspection	57°F, s	sunny	Inspection	9:00AM	Inspection end	9:45 AM
Inspector Name, Title Contact Information	&	Chanler Florian, Environmental cflorian@beta-inc.com	8603	297045		
Present Phase of Construction However, the entirety of the		Phase 1. NOTE: The access road However, the entirety of the Site establish the Site access road.				
Inspection Location		North Sturbridge Road Solar Fac	cility - Entirety of Site ((0 North Sturbridge Road, Charlt	on, MA 01507)	
Standard Frequency: ☐Every 7 days		may be subject to different inspect				
Increased Frequency Every 7 days a or Tier 3) Reduced Frequency:	r: and within	24 hours of a 0.25" rain (for area more than 14 calendar days ap	s of sites discharging	to sediment or nutrient-impaired	d waters or to wate	rs designated as Tier 2, Tier 2.5,
 □ Twice during first month, no more than 14 calendar days apart; then once more within 24 hours of a 0.25" rain (for stabilized areas on "linear construction sites") □ Once per month and within 24 hours of a 0.25" rain (for arid, semi-arid, or drought-stricken areas during seasonally dry periods or during drought) □ Once per month (for frozen conditions where earth-disturbing activities are being conducted) 						
Was this inspection triggered by a 0.25" storm event? Yes No If yes, how did you determined whether a 0.25" storm event has occurred? Rain gauge on site Weather station representative of site. Specify weather station source: Worcester Regional Airport						
Total rainfall amount that triggered the inspection (inches): 0.25" Was this inspection triggered by the occurrence of runoff from snowmelt sufficient to cause a discharge? Yes No						

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 03/15/2022

Jnsafe	Conditions	for	Inspection

Did you determine that any portion of your site was unsafe for inspection per CGP Part 4.1.5? \Bigsi Yes \Bigsi No If "yes", complete the following:

- Describe the conditions that prevented you from conducting the inspection in this location: N/A
- Location where conditions were found: N/A

Condition and Effectiveness of Erosion and Sediment (E&S) Controls (CGP Part 2.2)						
Type/Location of E&S Control	Maintenance Needed?*					
1. Silt Fence and Straw Wattles	No	No	1/28/ 2022	On 1/28/2022 Supreme repaired previously reported damage to silt fence and wattles at the Site.		
			2/2/ 2022	On 2/2/2022 BETA verified the repairs made by Supreme to be adequate with the specification.		
			3/15/ 2022	On 3/15/2022 BETA observed torn silt fence in multiple lo-		
Stabilized Construction Entrance (Site Entrance – Access Road)	No	No		cations along the perimeter of the Site. No discharge was observed. All of the wattles appear to be within		
3. Stump and Soil Stockpile Area	No	No		specification.		
4. Dust Controls	N/A	N/A				
5. Jute Mesh (Steep Slopes)	N/A	N/A				
6. Temporary Seeding	No	No				

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 03/15/2022

1spection Date: 03/15/2022													
 7. Topsoil Re-Use 8. Storm Drain Inlets (North Brookfield Road) 9. Temporary Drainage Swales (Throughout Site) 		N/A N/A N/A		N/A N/A N/A									
(Throughout Site) 10. Temporary Sediment Basins (Throughout Site)		N/A		N/A									
	,					of Pollution P		on (P2) Pra	<u>actices (C</u>	CGP Part 2	.3)		
Type/Location of P2 Practices [insert additional rows if applicable]	Mainte Neede	enance ed?*	Correc Action Require		Mainte Correc	n Which nance or tive Action entified?	Notes						
Equipment Refueling	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Staging Area 2. Hydraulic Lines	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Staging/Work Areas	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Equipment Maintenance Staging Area	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
4. Sanitary Toilets	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Staging Area 5. Vehicle Accident	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Entire Site	□Yes	⊠No	□Yes	⊠No	[Enter o	late]							

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 03/15/2022

Staging/Work Areas				
8. Concrete Washout	□Yes⊠No	□Yes⊠No	[Enter date]	

Stabilization of Exposed Soil (CGP Part 2.2.14)							
Stabilization Area [insert additional rows if applicable]	Stabilization Method	Have You Initiated Stabilization?	Notes				
Earthen access road leading to stockpile area	Straw mulch or hydroseed	⊠Yes 7/30/2021 □No	The stockpile area and associated access road have been hydroseeded. Germination has begun and the area will be monitored for successful establishment.				
Informal access road along northern portion of the Site	Straw mulch or hydroseed	□Yes [Enter date] ⊠No	Erosion channels are beginning to form within upgradient portions of the informal access road (Figure 1). The contractor indicated that stabilization by smoothing out soils and seeding or spreading mulch would occur on 7/30/2021. Stabilization of this area has not been initiated. After inspection of the area on 8/24/2021, it was determined that				

^{*} Note: The permit differentiates between conditions requiring routine maintenance, and those requiring corrective action. The permit requires maintenance in order to keep controls in effective operating condition. Corrective actions are triggered only for specific conditions, which include: 1) A stormwater control needs repair or replacement (beyond routine maintenance) if it is not operating as intended; 2) A stormwater control necessary to comply with the permit was never installed or was installed incorrectly; 3) You become aware that the stormwater controls you have installed and are maintaining are not effective enough for the discharge to meet applicable water quality standards or applicable requirements in Part 3.1; 4) One of the prohibited discharges in Part 1.3 is occurring or has occurred; or 5) EPA requires corrective actions as a result of a permit violation found during an inspection carried out under Part 4.8. If a condition on your site requires a corrective action, you must also fill out a corrective action form found at https://www.epa.gov/npdes/stormwater-discharges-construction-activities#resources. See Part 5 of the permit for more information.

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G Inspection Date: 03/15/2022

ispection bate. 03/13/2022	•	•	
			temporary swales would likely alleviate the issue of channelization in this area; however, these swales will not be constructed until work resumes at the Site in the spring (pending local approval). This area will continue to be monitored; however, stabilization is not required since the area is not discharging sediment beyond the limits of work.
Area beyond the limits of work at Discharge 1	Hand application of seed	⊠Yes 8/24/2021 □No	The sediment deposit previously observed has been removed from beyond the limits of work and the area has been seeded. No sediment migrated within 50 feet of a "water of the US". Straw and additional seed was applied on 8/24/2021.
			On 2/2/2022 BETA verified that grass seed had been successful established. BETA will continue to monitor grass growth in the spring.
Area beyond limits of work at Discharge 2	Hand application of seed	☐Yes Enter Date ☐No	

	Description of Discharges (CGP Part 4.6.6)
Was a stormwater discharge or other discharge of the following information for	each point of discharge:
Discharge Location	Observations
Discharge 1	Describe the discharge: NA At points of discharge and the channels and banks of surface waters in the immediate vicinity, are there any visible signs of erosion and/or sediment accumulation that can be attributed to your discharge? No Yes If yes, describe what you see, specify the location(s) where these conditions were found, and indicate whether modification, maintenance, or corrective action is needed to resolve the issue: NA

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G

Inspection Date: 03/15/2022

Contractor or Subcontractor Signature and Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature of Contractor or Subcontractor:

Printed Name and Affiliation:

Operator Signature and Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature of Operator or "Duly Authorized Representative":

Date:

Printed Name and Affiliation:

Chanler Florian

03/15/2022




Photo 1



View of area downgradient of Discharge 2—facing north west.

Photo 2



View of damaged silt fence in south east portion of the Site —facing south east

PHOTOGRAPHIC DOCUMENTATION
North Sturbridge Road Solar Facility
Charlton, Massachusetts
Photographs Documented 03.15.2022