Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 04/19/2022

		General Info	ormation						
45°F, cloudy		Inspection	2:00 PM	Inspection end	2:40 PM				
&	Chanler Florian, Environmental cflorian@beta-inc.com	•							
Inspection Location North Sturbridge Road Solar Facility - Entirety of Site (0 North Sturbridge Road, Charlton, MA 01507)									
,		·		,,,,,,					
/: and within	24 hours of a 0.25" rain (for area	s of sites discharging	to sediment or nutrient	-impaired waters or to wate	rs designated as Tier 2, Tier 2.5,				
<ul> <li>□ Twice during first month, no more than 14 calendar days apart; then once more within 24 hours of a 0.25" rain (for stabilized areas on "linear construction sites")</li> <li>□ Once per month and within 24 hours of a 0.25" rain (for arid, semi-arid, or drought-stricken areas during seasonally dry periods or during drought)</li> <li>□ Once per month (for frozen conditions where earth-disturbing activities are being conducted)</li> </ul>									
Was this inspection triggered by a 0.25" storm event?									
	execution  y (Note: you  nd within 2  and within  month, no month, no and within  (for frozer iggered by but determine on site  bunt that tri	Chanler Florian, Environmental cflorian@beta-inc.com Phase 1. NOTE: The access road.  However, the entirety of the Site establish the Site access road.  North Sturbridge Road Solar Fa  Y (Note: you may be subject to different inspect  and within 24 hours of a 0.25" rain or the occ  and within 24 hours of a 0.25" rain (for area  month, no more than 14 calendar days ap month, no more than 14 calendar days ap and within 24 hours of a 0.25" rain (for aric  (for frozen conditions where earth-disturbing iggered by a 0.25" storm event?  Weather station representation that triggered the inspection (inches): 0	Chanler Florian, Environmental Scientist (BETA Group cflorian@beta-inc.com 8603  Phase 1. NOTE: The access road and stabilized const However, the entirety of the Site has been cleared of establish the Site access road.  North Sturbridge Road Solar Facility – Entirety of Site of the Site hours of a 0.25" rain or the occurrence of runoff from the within 24 hours of a 0.25" rain (for areas of sites discharging month, no more than 14 calendar days apart; then once per month, no more than 14 calendar days apart; then once more and within 24 hours of a 0.25" rain (for arid, semi-arid, or drough offer frozen conditions where earth-disturbing activities are being iggered by a 0.25" storm event? Yes No ou determined whether a 0.25" storm event has occurred?  Son site Weather station representative of site. Specify we can the station representative of site.	Chanler Florian, Environmental Scientist (BETA Group, Inc.) cflorian@beta-inc.com 8603297045  Phase 1. NOTE: The access road and stabilized construction entrance has between the entirety of the Site has been cleared of trees. No grubbing/strestablish the Site access road.  North Sturbridge Road Solar Facility – Entirety of Site (0 North Sturbridge Road y (Note: you may be subject to different inspection frequencies in different areas of the site. Che and within 24 hours of a 0.25" rain or the occurrence of runoff from snowmelt sufficient to the sum of the sum of a 0.25" rain (for areas of sites discharging to sediment or nutrient month, no more than 14 calendar days apart; then once per month after first month; and within 24 hours of a 0.25" rain (for arid, semi-arid, or drought-stricken areas during and within 24 hours of a 0.25" rain (for arid, semi-arid, or drought-stricken areas during activities are being conducted) (aggered by a 0.25" storm event? Yes No but determined whether a 0.25" storm event has occurred?  Sum of the Storm event of site. Specify weather station source: sount that triggered the inspection (inches): 0.25"	Inspection 2:00 PM Inspection and Inspection				

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 04/19/2022

Unsafe Conditions for Inspection
----------------------------------

Did you determine that any portion of your site was unsafe for inspection per CGP Part 4.1.5? 

Yes No If "yes", complete the following:

- Describe the conditions that prevented you from conducting the inspection in this location: N/A
- Location where conditions were found: N/A

Condition and Effectiveness of Erosion and Sediment (E&S) Controls (CGP Part 2.2)						
Type/Location of E&S Control	Maintenance Needed?*	Corrective Action Required?*	Date on Which Maintenance or Corrective Action First Identified?	Notes		
Silt Fence and Straw Wattles	Yes	No	3/15/2022	On 4/19/2022 BETA observed damage to the wattles in the northeast and eastern corners of the Site, damage was first observed on 3/15/2022. BETA also observed the silt fence to be partly torn in the southeastern corner of the Site, damage was first observed on 3/27/2022. General maintenance is needed for the entire silt fence. No evidence of discharge was observed.		
Stabilized Construction Entrance     (Site Entrance – Access Road)	No	No				
3. Stump and Soil Stockpile Area	No	No				
4. Dust Controls	N/A	N/A				
5. Jute Mesh (Steep Slopes)	N/A	N/A				
6. Temporary Seeding	No	No				

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 04/19/2022

ispection bate. 04/19/2022													
7. Topsoil Re-Use 8. Storm Drain Inlets (North Brookfield Road) 9. Temporary Drainage Swall (Throughout Site) 10. Temporary Sediment Basin (Throughout Site)		N/A N/A N/A		N/A N/A N/A									
		Condit	ion and	Effectiv	eness c	of Pollution P	reventio	n (P2) Pr	actices (	CGP Part 2	2.3)		
Type/Location of P2 Practices [insert additional rows if applicable]	Maintena Needed	ance	Correct Action Require	tive	Date or Mainte Correc	n Which nance or tive Action entified?	Notes				,		
Equipment Refueling	□Yes ∣	⊠No	□Yes	⊠No	[Enter o	date]							
Staging Area  2. Hydraulic Lines	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Staging/Work Areas	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Equipment Maintenance     Staging Area	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
4. Sanitary Toilets	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Staging Area  5. Vehicle Accident	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Entire Site	. □Yes ∣	⊠No_	□Yes	⊠No	[Enter o	date]							

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 04/19/2022

Staging/Work Areas			
8. Concrete Washout	□Yes⊠No	□Yes⊠No	[Enter date]

Stabilization of Exposed Soil (CGP Part 2.2.14)									
Stabilization Area [insert additional rows if applicable]	Stabilization Method	Have You Initiated Stabilization?	Notes						
Earthen access road leading to stockpile area	Straw mulch or hydroseed	⊠Yes 7/30/2021 □No	The stockpile area and associated access road have been hydroseeded. Germination has begun and the area will be monitored for successful establishment.						
Informal access road along northern portion of the Site	Straw mulch or hydroseed	□Yes [Enter date] ⊠No	Erosion channels are beginning to form within upgradient portions of the informal access road (Figure 1). The contractor indicated that stabilization by smoothing out soils and seeding or spreading mulch would occur on 7/30/2021. Stabilization of this area has not been initiated. After inspection of the area on 8/24/2021, it was determined that						

<sup>\*</sup> Note: The permit differentiates between conditions requiring routine maintenance, and those requiring corrective action. The permit requires maintenance in order to keep controls in effective operating condition. Corrective actions are triggered only for specific conditions, which include: 1) A stormwater control needs repair or replacement (beyond routine maintenance) if it is not operating as intended; 2) A stormwater control necessary to comply with the permit was never installed or was installed incorrectly; 3) You become aware that the stormwater controls you have installed and are maintaining are not effective enough for the discharge to meet applicable water quality standards or applicable requirements in Part 3.1; 4) One of the prohibited discharges in Part 1.3 is occurring or has occurred; or 5) EPA requires corrective actions as a result of a permit violation found during an inspection carried out under Part 4.8. If a condition on your site requires a corrective action, you must also fill out a corrective action form found at <a href="https://www.epa.gov/npdes/stormwater-discharges-construction-activities#resources">https://www.epa.gov/npdes/stormwater-discharges-construction-activities#resources</a>. See Part 5 of the permit for more information.

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G Inspection Date: 04/19/2022

113.pcc11011 batc. 04/11/12022	•	•	
			temporary swales would likely alleviate the issue of channelization in this area; however, these swales will not be constructed until work resumes at the Site in the spring (pending local approval). This area will continue to be monitored; however, stabilization is not required since the area is not discharging sediment beyond the limits of work.
Area beyond the limits of work at Discharge 1	Hand application of seed	⊠Yes 8/24/2021 □No	The sediment deposit previously observed has been removed from beyond the limits of work and the area has been seeded. No sediment migrated within 50 feet of a "water of the US". Straw and additional seed was applied on 8/24/2021.
			On 10/2/2021 BETA verified that grass seed had been successful established. BETA will continue to monitor grass growth in the spring.
Area beyond limits of work at Discharge 2	Hand application of seed	☐Yes Enter Date ☐No	On 4/8/2022 BETA observed the recently seeded grass to be eshtablished.

Description of Discharges (CGP Part 4.6.6)						
Was a stormwater discharge or other discharge occurring from any part of your site at the time of the inspection?   No  Yes  If "yes", provide the following information for each point of discharge:						
Discharge Location	Observations					
Discharge 1	Describe the discharge: NA  At points of discharge and the channels and banks of surface waters in the immediate vicinity, are there any visible signs of erosion and/or sediment accumulation that can be attributed to your discharge?   No Yes  If yes, describe what you see, specify the location(s) where these conditions were found, and indicate whether modification, maintenance, or corrective action is needed to resolve the issue: NA					

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G

Inspection Date: 04/19/2022

#### Contractor or Subcontractor Signature and Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." Signature of Contractor or Subcontractor: Date: Printed Name and Affiliation: **Operator Signature and Certification** 


"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature of Operator or "Duly Authorized Representative":

Printed Name and Affiliation:

Chanler Florian

04/19/2022



## Photo 1



View of damaged silt fence in eastern portion of the Site —facing southeast

## Photo 2



View of damaged silt fence in southeast portion of the Site —facing northeast

PHOTOGRAPHIC DOCUMENTATION North Sturbridge Road Solar Facility Charlton, Massachusetts Photographs Documented 04.19.2022

# Photo 3



View of damaged wattle in northern portion of the Site —facing north

PHOTOGRAPHIC DOCUMENTATION North Sturbridge Road Solar Facility Charlton, Massachusetts Photographs Documented 04.19.2022