Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 03/24/2022

			General Info	ormation						
Weather conditions during inspection	47°F, c	cloudy	Inspection	2:00PM	Inspection end	2:45 PM				
Inspector Name, Title Contact Information	&	Chanler Florian, Environmental cflorian@beta-inc.com	8603	297045						
Present Phase of Con	struction		Phase 1. NOTE: The access road and stabilized construction entrance has been established pursuant to the Phase 1 scope of work.  However, the entirety of the Site has been cleared of trees. No grubbing/stumping has occurred other than that required to							
Inspection Location		North Sturbridge Road Solar Fac	cility - Entirety of Site	(0 North Sturbridge Road, Charl	ton, MA 01507)					
Standard Frequency:  Every 7 days	_	may be subject to different inspect								
Increased Frequency Every 7 days or Tier 3) Reduced Frequency: Twice during first Twice during first	r: and within month, no month, no	24 hours of a 0.25" rain (for area more than 14 calendar days ap more than 14 calendar days ap	s of sites discharging part; then once per m part; then once more	to sediment or nutrient-impaired nonth after first month; (for stabil within 24 hours of a 0.25" rain (f	d waters or to wate lized areas) for stabilized areas	on "linear construction sites")				
· ·		n 24 hours of a 0.25" rain (for aric n conditions where earth-disturbi	•		ally dry periods or d	luring drought)				
Was this inspection triggered by a 0.25" storm event?										

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 03/24/2022

Insafe	Conditions	for	Inspection
Jusaic	Conditions	101	ii ispeciioi i

Did you determine that any portion of your site was unsafe for inspection per CGP Part 4.1.5? 

Yes No If "yes", complete the following:

- Describe the conditions that prevented you from conducting the inspection in this location: N/A
- Location where conditions were found: N/A

	Condition and	Effectiveness o	f Erosion and Sedim	ent (E&S) Controls (CGP Part 2.2)
Type/Location of E&S Control	Maintenance Needed?*			
Silt Fence and Straw Wattles	Nov	No	1/28/ 2022	On 1/28/2022 Supreme repaired previously reported damage to silt fence and wattles at the Site.
			2/2/ 2022	On 2/2/2022 BETA verified the repairs made by Supreme to be adequate with the specification.
			3/15/ 2022	On 3/15/2022 BETA observed torn silt fence in multiple lo-
Stabilized Construction Entrance     (Site Entrance – Access Road)	No	No		cations along the perimeter of the Site. No discharge was observed. All of the wattles appear to be within
3. Stump and Soil Stockpile Area	No	No		specification.
4. Dust Controls	N/A	N/A	3/24/2022	On 3/24/2022 BETA observed prey damaged silt fence in the south corner and norther tions of the Site. No evidence of discharge was observed.
5. Jute Mesh (Steep Slopes)	N/A	N/A		
6. Temporary Seeding	No	No		

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 03/24/2022

1spection Date: 03/24/2022													
<ul> <li>7. Topsoil Re-Use</li> <li>8. Storm Drain Inlets     (North Brookfield Road)</li> <li>9. Temporary Drainage Swales     (Throughout Site)</li> </ul>		N/A N/A N/A		N/A N/A N/A									
10. Temporary Sediment Basir (Throughout Site)	ns	N/A		N/A									
		Candi	Han and	I Eff a a thu		of Pollution P	rovonti	, (D2) Dra	ations (C)		1		
Type/Location of P2 Practices [insert additional rows if applicable]	Mainte Neede	enance	Correc Action Require	tive	Date or Mainte Correc	n Which nance or tive Action entified?	Notes	)	<u>circes (ex</u>	Of Full 2.5	,		
Equipment Refueling	□Yes	⊠No	□Yes	⊠No	[Enter o	late]							
Staging Area  2. Hydraulic Lines	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Staging/Work Areas	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Equipment Maintenance     Staging Area	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
4. Sanitary Toilets	□Yes	⊠No	□Yes	⊠No	[Enter o	late]							
Staging Area  5. Vehicle Accident	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							
Entire Site	□Yes	⊠No	□Yes	⊠No	[Enter o	date]							

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 03/24/2022

Staging/Work Areas				
8. Concrete Washout	□Yes⊠No	□Yes⊠No	[Enter date]	

Stabilization of Exposed Soil (CGP Part 2.2.14)							
Stabilization Area [insert additional rows if applicable]	Stabilization Method	Have You Initiated Stabilization?	Notes				
Earthen access road leading to stockpile area	Straw mulch or hydroseed	⊠Yes 7/30/2021 □No	The stockpile area and associated access road have been hydroseeded. Germination has begun and the area will be monitored for successful establishment.				
Informal access road along northern portion of the Site	Straw mulch or hydroseed	□Yes [Enter date] ⊠No	Erosion channels are beginning to form within upgradient portions of the informal access road (Figure 1). The contractor indicated that stabilization by smoothing out soils and seeding or spreading mulch would occur on 7/30/2021. Stabilization of this area has not been initiated. After inspection of the area on 8/24/2021, it was determined that				

<sup>\*</sup> Note: The permit differentiates between conditions requiring routine maintenance, and those requiring corrective action. The permit requires maintenance in order to keep controls in effective operating condition. Corrective actions are triggered only for specific conditions, which include: 1) A stormwater control needs repair or replacement (beyond routine maintenance) if it is not operating as intended; 2) A stormwater control necessary to comply with the permit was never installed or was installed incorrectly; 3) You become aware that the stormwater controls you have installed and are maintaining are not effective enough for the discharge to meet applicable water quality standards or applicable requirements in Part 3.1; 4) One of the prohibited discharges in Part 1.3 is occurring or has occurred; or 5) EPA requires corrective actions as a result of a permit violation found during an inspection carried out under Part 4.8. If a condition on your site requires a corrective action, you must also fill out a corrective action form found at <a href="https://www.epa.gov/npdes/stormwater-discharges-construction-activities#resources">https://www.epa.gov/npdes/stormwater-discharges-construction-activities#resources</a>. See Part 5 of the permit for more information.

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G Inspection Date: 03/24/2022

ispection bate. 03/24/2022			
			temporary swales would likely alleviate the issue of channelization in this area; however, these swales will not be constructed until work resumes at the Site in the spring (pending local approval). This area will continue to be monitored; however, stabilization is not required since the area is not discharging sediment beyond the limits of work.
Area beyond the limits of work at Discharge 1	Hand application of seed	⊠Yes 8/24/2021 □No	The sediment deposit previously observed has been removed from beyond the limits of work and the area has been seeded. No sediment migrated within 50 feet of a "water of the US". Straw and additional seed was applied on 8/24/2021.  On 2/2/2022 BETA verified that grass seed had been successful established. BETA will continue to monitor grass growth in the spring.
Area beyond limits of work at     Discharge 2	Hand application of seed	☐Yes Enter Date ☐No	

Description of Discharges (CGP Part 4.6.6)						
Was a stormwater discharge or other discharge of the following information for	each point of discharge:					
Discharge Location	Observations					
Discharge 1	Describe the discharge: NA  At points of discharge and the channels and banks of surface waters in the immediate vicinity, are there any visible signs of erosion and/or sediment accumulation that can be attributed to your discharge?   No Yes  If yes, describe what you see, specify the location(s) where these conditions were found, and indicate whether modification, maintenance, or corrective action is needed to resolve the issue: NA					

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G

Inspection Date: 03/24/2022

### Contractor or Subcontractor Signature and Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." Signature of Contractor or Subcontractor: Date: Printed Name and Affiliation: **Operator Signature and Certification** "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the

best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."


Signature of Operator or "Duly Authorized Representative":

Date:

Printed Name and Affiliation:

Chanler Florian

03/24/2022



# Photo 1



View of area downgradient of Discharge 2—facing south west.

## Photo 2



View of damaged silt fence in south east portion of the Site —facing south east

PHOTOGRAPHIC DOCUMENTATION
North Sturbridge Road Solar Facility
Charlton, Massachusetts
Photographs Documented 03.24.2022

# Photo 3



View of damaged silt fence in northern portion of the Site—facing north west.

## Photo 4



View of damaged silt fence in south east portion of the Site —facing south east

PHOTOGRAPHIC DOCUMENTATION
North Sturbridge Road Solar Facility
Charlton, Massachusetts
Photographs Documented 03.24.2022