Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

Inspection Date: 5/4/2022

			General Info	ormation					
Weather conditions during inspection	55°F, d	cloudy	Inspection start	1:20 PM	Inspection end	2:00 PM			
Inspector Name, Title Contact Information	&	Chanler Florian, Environmental cflorian@beta-inc.com	8603	297045	•				
Present Phase of Construction		Phase 1. NOTE: The access road and stabilized construction entrance has been established pursuant to the Phase 1 scope of work. However, the entirety of the Site has been cleared of trees. No grubbing/stumping has occurred other than that required to establish the Site access road.							
Inspection Location		North Sturbridge Road Solar Fa	cility - Entirety of Site ((0 North Sturbridge Road, Charlt	on, MA 01507)				
Standard Frequency: ☐Every 7 days		in may be subject to different inspects. 4 hours of a 0.25" rain or the occ							
Increased Frequency Every 7 days a or Tier 3) Reduced Frequency:	r: and within	24 hours of a 0.25" rain (for area	s of sites discharging	to sediment or nutrient-impaired	d waters or to wate	rs designated as Tier 2, Tier 2.5,			
 □ Twice during first month, no more than 14 calendar days apart; then once more within 24 hours of a 0.25" rain (for stabilized areas on "linear construction sites □ Once per month and within 24 hours of a 0.25" rain (for arid, semi-arid, or drought-stricken areas during seasonally dry periods or during drought) □ Once per month (for frozen conditions where earth-disturbing activities are being conducted) 									
Was this inspection triggered by a 0.25" storm event? ⊠ Yes □ No If yes, how did you determined whether a 0.25" storm event has occurred? □ Rain gauge on site ⊠ Weather station representative of site. Specify weather station source: Worcester Regional Airport									
		ggered the inspection (inches): (d by the occurrence of runoff fro		t to cause a discharge? 🛚 Ye	s 🛭 No				

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 5/4/2022

Unsafe Conditions for Inspectior	Jnsafe Cor	nditions	for	Inspection
----------------------------------	------------	----------	-----	------------

Did you determine that any portion of your site was unsafe for inspection per CGP Part 4.1.5?

Yes
No If "yes", complete the following:

- Describe the conditions that prevented you from conducting the inspection in this location: N/A
- Location where conditions were found: N/A

Condition and Effectiveness of Erosion and Sediment (E&S) Controls (CGP Part 2.2)						
Type/Location of E&S Control	Maintenance Needed?*					
1. Silt Fence and Straw Wattles	Yes	Y	1/28/ 2022 2/2/ 2022	On 1/28/2022 Supreme repaired previously reported damage to silt fence and wattles at the Site. On 2/2/2022 BETA verified the repairs made by Supreme.		
 Stabilized Construction Entrance (Site Entrance - Access Road) Stump and Soil Stockpile Area Dust Controls Jute Mesh (Steep Slopes) Temporary Seeding 	No No N/A N/A No	No No N/A N/A No	3/15/ 2022	On 3/1 22 BETA observed torn silt fence in multiple locations along the perimeter of the Site. The silt wattles are still serving their intended purpose but require maintenance. On 3/24/2022 BETA observed damaged silt fence in the southeast corner and northern portions of the Site. No evidence of discharge was observed.		

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

NPDES ID No.: MAR10031G Inspection Date: 5/4/2022

ispection bate. 3/4/2022							
7. Topsoil Re-Use 8. Storm Drain Inlets (North Brookfield Road) 9. Temporary Drainage Swal (Throughout Site) 10. Temporary Sediment Basin (Throughout Site)		A A	N/A N/A N/A		4/1/2022 4/8/2022		On 4/1/2022 BETA observed repairs on the collapsed portions of the silt fence located in the north east corner. BETA observed damage to the silt fence and wattle in the north east corner of the Site. No evidence of discharge was observed. On 4/8/2022 BETA observed torn silt fence in the eastern portion of the Site, No evidence of discharge was observed.
					4/27/2022		On 4/27/2022 BETA observed damage to the wattles in the northeast and east corners of the Site. No evidence of discharge was observed.
	Co	ndition an	d Effectiv	anass (of Pollution P	roventic	on (P2) Practices (CGP Part 2.3)
Type/Location of P2 Practices [insert additional rows if applicable]	Maintenanc Needed?*	e Correc Actior Requir	ctive I	Date o Mainte Correc	n Which enance or etive Action entified?	Notes	511 (1 2) 1 1 d (1 0 0 1 1 d (1 2 0)
Equipment Refueling	□Yes ⊠N	o \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ Yes	⊠No	[Enter	date]		
Staging Area 2. Hydraulic Lines	□Yes ⊠N	o ☐Yes	⊠No	[Enter o	date]		
Staging/Work Areas	□Yes ⊠N	o \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	⊠No	[Enter of	date]		
Equipment Maintenance Staging Area	□Yes ⊠N	o ☐Yes	⊠No	[Enter o	date]		
4. Sanitary Toilets	□Yes ⊠N	o \ \ \ \ \ \ \ \ \ \ \ \ Yes	⊠No	[Enter	date]		
Staging Area 5. Vehicle Accident	□Yes ⊠N	o ☐Yes	⊠No	[Enter o	date]		
Entire Site	. □Yes ⊠N	o □Yes	⊠No	[Enter of	date]	•	

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G Inspection Date: 5/4/2022

Staging/Work Areas				
8. Concrete Washout	□Yes⊠No	□Yes⊠No	[Enter date]	

Stabilization of Exposed Soil (CGP Part 2.2.14)								
Stabilization Area [insert additional rows if applicable]	Stabilization Method	Have You Initiated Stabilization?	Notes					
Earthen access road leading to stockpile area	Straw mulch or hydroseed	⊠Yes 7/30/2021 □No	The stockpile area and associated access road have been hydroseeded. Germination has begun and the area will be monitored for successful establishment.					
Informal access road along northern portion of the Site	Straw mulch or hydroseed	□Yes [Enter date] ⊠No	Erosion channels are beginning to form within upgradient portions of the informal access road (Figure 1). The contractor indicated that stabilization by smoothing out soils and seeding or spreading mulch would occur on 7/30/2021. Stabilization of this area has not been initiated. After inspection of the area on 8/24/2021, it was determined that					

^{*} Note: The permit differentiates between conditions requiring routine maintenance, and those requiring corrective action. The permit requires maintenance in order to keep controls in effective operating condition. Corrective actions are triggered only for specific conditions, which include: 1) A stormwater control needs repair or replacement (beyond routine maintenance) if it is not operating as intended; 2) A stormwater control necessary to comply with the permit was never installed or was installed incorrectly; 3) You become aware that the stormwater controls you have installed and are maintaining are not effective enough for the discharge to meet applicable water quality standards or applicable requirements in Part 3.1; 4) One of the prohibited discharges in Part 1.3 is occurring or has occurred; or 5) EPA requires corrective actions as a result of a permit violation found during an inspection carried out under Part 4.8. If a condition on your site requires a corrective action, you must also fill out a corrective action form found at https://www.epa.gov/npdes/stormwater-discharges-construction-activities#resources. See Part 5 of the permit for more information.

Inspection Report for North Sturbridge Road Solar Facility NPDES ID No.: MAR10031G

Inspection Date: 5/4/2022

113pection bate. 3/4/2022	•	•	
			temporary swales would likely alleviate the issue of channelization in this area; however, these swales will not be constructed until work resumes at the Site in the spring (pending local approval). This area will continue to be monitored; however, stabilization is not required since the area is not discharging sediment beyond the limits of work.
Area beyond the limits of work at Discharge 1	Hand application of seed	⊠Yes 8/24/2021 □No	The sediment deposit previously observed has been removed from beyond the limits of work and the area has been seeded. No sediment migrated within 50 feet of a "water of the US". Straw and additional seed was applied on 8/24/2021.
			On 10/2/2021 BETA verified that grass seed had been successful established. BETA will continue to monitor grass growth in the spring.
Area beyond limits of work at Discharge 2	Hand application of seed	☐Yes Enter Date ☐No	On 4/27/2022 BETA observed the recently seeded grass to be thriving.



Description of Discharges (CGP Part 4.6.6) Was a stormwater discharge or other discharge occurring from any part of your site at the time of the inspection? □No ☑Yes If "yes", provide the following information for each point of discharge:					
Discharge Location Observations					
Discharge 1	Describe the discharge: NA At points of discharge and the channels and banks of surface waters in the immediate vicinity, are there any visible signs of erosion and/or sediment accumulation that can be attributed to your discharge? No Yes If yes, describe what you see, specify the location(s) where these conditions were found, and indicate whether modification, maintenance, or corrective action is needed to resolve the issue: NA				

Inspection Report for North Sturbridge Road Solar Facility

NPDES ID No.: MAR10031G

Inspection Date: 5/4/2022

Contractor or Subcontractor Signature and Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature of Contractor or Subcontractor:

Date:

Printed Name and Affiliation:

Operator Signature and Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature of Operator or "Duly Authorized Representative":

Date:

Printed Name and Affiliation:

Chanler Florian

5/4/2022




Photo 1



View of damaged silt fence in eastern portion of the Site — facing sout

Photo 2



View of damaged silt fence in south portion of the Site — facing south east

PHOTOGRAPHIC DOCUMENTATION North Sturbridge Road Solar Facility Charlton, Massachusetts Photographs Documented 5.4.2022

Photo 3



View of damaged silt wattle in northern portion of the Site — facing north

Photo 4



View of damaged silt wattle in north portion of the Site — facing north

PHOTOGRAPHIC DOCUMENTATION North Sturbridge Road Solar Facility Charlton, Massachusetts Photographs Documented 5.4.2022

Photo 5



View of seeded grass at Discharge 2 — facing north

PHOTOGRAPHIC DOCUMENTATION North Sturbridge Road Solar Facility Charlton, Massachusetts Photographs Documented 5.4.2022